JULIO OLIVEIRA, ABB POWER GRIDS – GRID AUTOMATION, AUGUST 08TH

Gestão de ativos em subestações digitais

ABB Ability – Plataforma Ellipse

Agenda

- Os desafios correntes encontrados pelas concessionárias
- O cenário atual das subestações quanto à digitalização
- Estado da arte da norma IEC 61850
- Gestão de ativos na era das subestações digitais

Os desafios correntes encontrados pelas concessionárias de energia

O cenário atual das subestações quanto à digitalização

Como o escopo da digitalização é entendido entre as concessionárias

Oportunidades para explorar com as Subestações Digitais

- Barramento de processo
- Cyber segurança
- Teleproteção com MPLS/TP
- Medidores sincrofasoriais PMU
- Gestão de ativos
- Comunicação WiFi por meio de redes MESH

Aderência às normas

Além da redundância, sincronismo e performance ...

Funcionalidades e recursos mencionados

IEC 61850-5 Communication networks and systems for power utility automation - Part 5: Communication requirements for functions and device models	IEC 61850-6 Communication networks and systems for power utility automation - Part 6: Configuration description language for communication in electrical substations related to IEDs	IEC 61850-8-1: Communication networks and systems for power utility automation - Part 8-1: Specific communication service mapping (SCSM) - Mappings to MMS (ISO 9506-1 and ISO 9506-2) and to ISO/IEC 8802-3
IEC 61850-9-2 Communication networks and systems for power utility automation - Part 9-2: Specific communication service mapping (SCSM) - Sampled values over ISO/IEC 8802-3	IEC/IEEE 61850-9-3 Communication networks and systems for power utility automation - Part 9-3: Precision time protocol profile for power utility automation	IEC 62439-3 Redline version Industrial communication networks - High availability automation networks - Part 3: Parallel Redundancy Protocol (PRP) and High-availability Seamless Redundancy (HSR)
IEC 62351 Series Power systems management and associated information exchange - Data and communications security - ALL PARTS	IEEE STANDARD Corrigendum to IEEE Std 802.3-2015 as amended by IEEE Std 802.3bw-2015, IEEE Std 802.3by-2016, IEEE Std 802.3bq-2016, IEEE Std 802.3bp-2016, IEEE Std 802.3br-2016, IEEE Std 802.3bn-2016, IEEE Std 802.3bz-2016, IEEE Std 802.3bu-2016, IEEE Std 802.3bv-2017 - IEEE Standard for Ethernet - Corrigendum 1: Multi-lane Timestamping
IEEE STANDARD IEEE Std 1588-2008 (Revision of IEEE Std 1588-2002) - IEEE Standard for a Precision Clock Synchronization Protocol for Networked Measurement and Control Systems		

Gestão de ativos na era da subestação digital

Plataforma ABB Ability Ellipse

Historiador

Inspeções manuais

Asset Performance Management

Modelo de transformadores

Asset Performance Management

Modelos

1. Transformadores e reatores
2. Disjuntores
3. Baterias de subestação
4. Linhas de transmissão
5. Banco de capacitores
6. TC e TP
7. Cabos subterrâneos
8. Modelos em desenvolvimento:
 - relé, religadores, turbinas eólicas

9. Open Model Interface

10. Machine Learning

Asset risk

12 locations covered

6 asset types

75 assets monitored

0 assets not monitored

766h last data updated

Spatial view

Issues

■ New ■ No actions ■ On track
 ■ Completed ■ At risk ■ Overdue

Most important issues

- Subsystem Accessory Alert
CBK.GLD142825 5 months ago
- Subsystem Dielectric Alert
CBK.GLD142825
- Subsystem Mechanical Alert
CBK.GLD142825 5 months ago
- Subsystem Wear Information
CBK.889909
- Subsystem Mechanical Warning
CBK.889909

Explore →

Analytics

Assets by Type

■ Low ■ Medium ■ High ■ Unknown

Key risk changes

Increased

Decreased

ⓘ XFM.GLD1629568 - GLD1629568

Risk

Parameters

7/17

Data Quality

1

Remaining useful life

Coming Soon

More Detail

Analytics ▾

Risk Matrix

Condition	10.9
Importance	65
Last update	last month

Action Plan

last month **ON TRACK**

▲ Oil quality issue detected

last month **OVERDUE**

▲ Oil quality issue detected

2 years ago **ON TRACK**

▲ DGA miscellaneous issue(s)

2 years ago **OVERDUE**

▲ DGA issue(s) / Duval Triangle diagnostic

Risk Trend

Accessory	2.0
Dielectric	5.3
High Temperature	3.2
Miscellaneous	0.0
Short Circuit	0.3

MSEWOT - Update Work Order

Submit Refresh New Save As Delete Open New Search Navigate Actions

- 00006448 Indication of high moistu
- 001 Dielectric Frequency Respon

Work Order: 00006448 **AUTHORISED**

District Code: 0002 WORLD WIDE CORPORATION

Equipment Reference: GLD1629568

GSU TRANSFORMER 765KV MILLER SUBSTATION

Component Code: [] Component Modifier Code: []

Work Segment From: [] Work Segment To: []

Standard Job: 000058 [] [E] DFR Test

Work Order Desc: Indication of high moisture content in

User Status: []

Initiation Planning Map Location Location Extended Text Risk Scheduling Costs Actuals Vs Estimates Job Codes Completion Completion

Work Order Type: MT Maintenance Maintenance Type: MR Reactive

Work Group: 236 WORK GROUP 1

Account Code: 2125430 TRANSMISSION MTCE SOUTH MAINTENANCE

Related Work Order: []

Originator: 0000000097 Paul Walk

Originating Document Type: [] Originating Document Number: []

Work Request: 000000005728 INDICATION OF HIGH MOISTURE CONTENT IN

Raised Date: 08/11/2017 Raised Time: 00:39:06

MSSS Status: [] Lock Integration Updates: []

Tasks

WO Task	WO Task Desc	Task Dur Ho	Task Status	Plan Start Date	Plan Start Ti	Plan Finish D
001	Dielectric Frequency Response Test		Authorised			

Complete Release Work

0 selected 1 - 1

Wearables

Apoio à manutenção

Contatos

Marcos Vilela
Engenheiro de soluções
(31) 9285-6655
marcos.vilela@br.abb.com

Julio Oliveira
Gerente de tecnologia
(11) 98112-0419
julio.Oliveira@br.abb.com

ABB